

FC Bare Fiber Adapter

Features	
Low insertion loss Good repeatability Easy operation	
Application	
Temporarily connect to bare fiber Fiber testing in lab Production line of optical fiber devices	

Specifications:

Parameter	Type
Ferrule ID (mm)	0.126 ~ 0.127
Ferrule OD (mm)	2.499
Insertion loss (dB)	≤0.02
Repeatability (dB)	≤0.02
Spring pulling force (dB)	200g
Fiber type	Φ125um SM or MM fiber
Plug times	≥10000 times
Operation temperature	-40 ~ 85 °C

Ordering Information

BFA-FC